

Date of Inspection : 03-12-2020		District: Buxar
Division : Dumaraon		Length (km):
Name of the Road: NH84 to Deouli Purab Tola (Gahauna)		
Scheme/Programme:	MAINTENANCE	MR-3054
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <b>Completed</b>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.R.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.R.
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*Handwritten:*  
 3/12/20  
 J. E.  
 Brahmapur

(Signature)

NAME:

DESIGNATION: