

FIELD INSPECTION REPORT


Date of Inspection :- 3.12.20		District :- Moga
Division :- Moga		Length (Km) :- 2.45
Name of Road :- Bahadurpur se sonihar		
Scheme/Programme :- old. MR		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- under maintenance.		Ongoing/Complete/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of :-		New Connectivity/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	SRI S/U
c)	Riding Quality	SRI S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA Yes/No <input checked="" type="checkbox"/>
f)	Construction Joints provided or not (CC Pavement)	HA Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)


 3.12.20
 SE/Alamb.