

# FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District : Purnea	
Division : Purnea		Length (Km) : 8.56 KM	
Name of the Road : Repair of road from Jageli Chowk Singhiya Charariya (Bime).			
Scheme/Programme :		Maintenance 3054 (MR) OLD	
Package No. : —		Road ID No. : —	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
SL No	Parameters to be Checked		Remarks
1).	<b>Pavement</b>		
a)	Road Junction condition		S/U ✓
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U ✓
d)	Road Camber		S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No } r.A.
f)	Contraction Joints provided or not (CC Pavement)		Yes/No }
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No ✓
2).	<b>Cross Drainage</b>		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U ✓
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U ✓
3).	<b>Road Furniture</b>		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No ✓
4).	<b>Compliance History</b>		
a)	Status of ATR's & any others		r.A.

Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	(U)

Name : Chandan Kumar Bhargav  
 Designation : Assistant Engineer

(Signature) *Chandran*  
 07/12/2020