

FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	Siwan
Division :	Siwan-01	Length (km):	3.300 km
Name of the Road:	Aaranda to Basantnagar		
Scheme/Programme:	MAINTENANCE		MR 3054
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance ✓		
Work is a case of:	New Connectivity Upgradation Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S ✓ S1
b)	Condition of Surfacing	S ✓ S1
c)	Riding Quality	S ✓ S1
d)	Road Camber	S ✓ S1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Not Provided
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S, SRI1 S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI1 Net Provided
c)	Condition of railings/slab/approach for Bridges	S SRI1 NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

'S'

Raveel
31/12/2020
JE
(Signature)

NAME: Ravindra Kumar Mandal
Junior Engineer