

FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020 District: Siwan
 Division : Siwan -01 Length (km):
 Name of the Road: Bhathui de Sarawe
 Scheme/Programme: MAINTENANCE MR 3054
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance is being done.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S S
b)	Condition of Surfacing	✓ S S
c)	Riding Quality	✓ S S
d)	Road Camber	✓ S S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No S
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI S
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	✓ S/SRI S
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No yes
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shambhu

(Signature)

NAME: Shambhu Kumar Thakur
 Junior Engineer