

FIELD INSPECTION REPORT

Date of Inspection: 05.12.2020		District:- Sitamarhi.	
Division:- RWD, Works Div. Pupri.		Length (km):- 8.00	
Name of the Road:- Nawahi Chowk NH 104 to Matauna			
Scheme/Programme:-		MAINTENANCE	
Package No.:- MR (3054)		Road Id No.: 31607808064	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railing/slab/approach for bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- Bijay Kumar Pandey

Bijay Kumar Pandey
05/12/2020
(Signature)

DESIGNATION:- JE