

FIELD INSPECTION REPORT

Date of Inspection: 05.12.2020

District: Madhyabani

Division: Madhyabani

Length (km): 4.100 km

Name of the Road: Maimal PWD Road to Pursauliya

Scheme Programme: MAINTENANCE

Package No.

Road Id No.

Status of the Project: ☒ Not yet completed ☐ Not yet started

Work is a case of: ☒ New ☐ Rehabilitation ☐ Improvement ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Is the Pavement regular?	☒
b)	Condition of Surfacing	☒
c)	Riding Quality	☒
d)	Gravel Chamber	☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes ☒ No ☐
f)	Contraction Joints provided or not (CC Pavement)	Yes ☒ No ☐
g)	Compaction of flank slope & raincuts if any	Yes ☒ No ☐
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U M/
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U M/
c)	Condition of railings/slab approach for Bridges	S SRI U M/
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes ☒ No ☐
4.	Compliance History	
a)	Status of ATR's & any others	Rb ATR

Overall Rating: *Surfacing work in some stretches is in progress.*

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
5.12.20
(Signature)

NAME: *Sanjay Kumar*
Assistant Engineer