


FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020	District : - Madhubani
Division : - Madhubani	Length (km):- 5.100 km
Name of the Road: - Kharauli Bagar Baroti mch to chaur to Mainepatti.	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	☒ Ongoing/Completed/Under Maintenance
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 5/12/20.
 (Signature)

NAME: Vijay Kumar Thakur
 DESIGNATION: Junior Engineer.