

FIELD INSPECTION REPORT

Date of Inspection: 6/12/20 District: Samaspur
 Division: Samaspur Length (km):
 Name of the Road: X. Road Lohri to Chaurpur
 Scheme Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SR/U
c)	Condition of railings/slab/approach for Bridges	✓ SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR & any others	ND

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U)

S

(Signature)

NAME:

Arjun Kumar

DESIGNATION:

J.E