


FIELD INSPECTION REPORT


Date of Inspection : 6.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 1.50	
Name of the Road : Asarganj RCD Road to Deodha.			
Scheme / Programme : MAINTENANCE			
Package No. :		Road Id No. :	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	S/UV	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NH
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / Informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating :			
Satisfactory (S)		—	
Satisfactory but requires Improvement (SRI)		—	
Unsatisfactory (U)		U	

Not - B.T. Crumpled & damaged in both parts 2 Borel painting not maintained, No Bush cutting.

NAME: Rajib Kumar Rajan

DESIGNATION: A.E

(Signature) 
6.12.2020
A.E


6/12/2020
m