

FIELD INSPECTION REPORT

Date Of Inspection 02/12/2020		District Bhojpur
Division Piro		Length (km): 10.55 Km
Name of the Road: Bachari Trimuhan to Bhagwanpur Pul		
Scheme/Programme MAINTENANCE		
Package No.:		Road Id No.: 10401800816
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/Maintenance
SI No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	137
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name:

Kamlesh Kumar

Designation

J-E

Kamlesh Kumar
02/12/2020
(Signature)