

FIELD INSPECTION REPORT

Date Of Inspection 2/12/2020		District Bhojpur
Division Piro		Length (km): 14.76
Name of the Road: Nan Sagar to Belaur Banglaw Path.		
Scheme/Programme MAINTENANCE		
Package No.:		Road Id No.: 10401800817
Status of the Project :		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of :		New Connectivity/Up gradation/Maintenance
SI No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U <input checked="" type="checkbox"/>
b)	Condition of Surfacing	S/U <input checked="" type="checkbox"/>
c)	Riding Quality	S/U <input checked="" type="checkbox"/>
d)	Road Camber	S/U <input checked="" type="checkbox"/>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <input checked="" type="checkbox"/>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <input checked="" type="checkbox"/>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N-A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N-A S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <input checked="" type="checkbox"/>
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Name:

Kamlesh Kumar

Designation

J-E

K. Kumar
2/12/20
(Signature)