

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020	District: Patna
Division : Besh.	Length (km): 2.20 km
Name of the Road: Jhachak Baulapur path to Imadpur.	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & ranscut if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls of frame pipe culverts including its painting	S SRII
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRII
c)	Condition of railing/slab approach for Bridges	S SRII
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/1km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bishnu Pratap Singh
Junior Engineer.
NAME:

BK
04/12/2020
(Signature)