## FIELD INSPECTION REPORT

Length (km):
nelations - Saxua abad, RCD Road Pool-1
ICE
Road Id No.:
pleted/Under Maintenance
vity/Up gradution/ Maintenance

SI. No.	Parameters to be cheeked	Remarks	
1.	Pavement		
a)	Road Junction condition	SAT	
b)	Condition of Surfacing	<b>J87</b> U	
c)	Riding Quality	_8/U	
d)	Road Camber	_S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YestNo	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	_S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_8/SRI/U	
c)	Condition of railings/slab/approach for Bridges	-8/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No:	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

OZ/R/2019 · (Signature)

NAME:

CHANDAN KUMAL

DESIGNATION:

7.6