

FIELD INSPECTION REPORT

Date of Inspection : 7/12/20		District: Madhepura
Division : Madhepura		Length (km): 2.70 K.M
Name of the Road: Kumarkhand to Jaduapatti		
Scheme/Programme: MAINTENANCE		MR 3054 (old)
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ☒
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ☒
b)	Condition of Surfacing	S/U ☒
c)	Riding Quality	S/U ☒
d)	Road Camber	S/U ☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ☒
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ☒
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ☒
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	☒
Unsatisfactory (U)	

Birendra Kumar
J.E., Kumarkhand
NAME:

Birend
07/12/20
(Signature)