FIELD INSPECTION REPORT

Date of Inspection:	112/2020	District: James	
Division: 1920u Length (km): 5.500			
Name of the Road: Ha	erdi morto	Bhoten	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.: 20804100	856
		d/Under Maintenance	
		Up gradation/ Maintenance	amorana antonia della
SI No.	Parameters	Chian same and the regularity of the first transfer of the first t	Remarks
1. Payement			
a) Road Junction of	Road Junction condition		
b) Condition of Su	Condition of Surfacing		
c) Riding Quality	Riding Quality		
d) Road Camber	Road Camber		
6)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Contraction Joi	Contraction Joints provided or not (CC Pavement)		
g) Compaction of	Compaction of flank/slope & raincuts if any		
2. Terose Desinar	Correction of the Correction o		
a) Condition of he	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts		
c) Condition of ra	Condition of railings/slab/approach for Bridges		
Roid Cirollan	10		
a) Whether sign stones/Pavemen	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
This compliance is	isiony + 7.	MACHINE THE STATE OF THE STATE	
a) Status of ATR'	Status of ATR's & any others		
		ong	oing .
Overall Rating :			

Ons	101117
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

7/12/2020 (Signature)1.6

NAME:

DESIGNATION: