

FIELD INSPECTION REPORT

Date of Inspection : 5/12/2016	District: palna.
Division : Borth.	Length (km): 8.85 km.
Name of the Road: Benuabasa to chakgalal path.	
Scheme Programme: MAINTENANCE	Road ID No.:
Package No.:	Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
Work is a case of:	New Connectivity ☐ Up gradation ☐ Maintenance ☒

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank/slope & (incuts if any)	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	main board ✓ caution board ✓ biral ✓
4.	Compliance History	
a)	Status of ATR's & any others	"S"

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Bishwajit Singh
Junior Engineer.
NAME:

BK
09/12/2016
(Signature) J E