


# FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.900
Name of Road : Of Road Bhatgama Railway Crossing Dhala No-31 to Satha Border		
Scheme / Programme:	MAINTENANCE	
Package No:-	Road Id No: -	
Status of the Project: <b>Under Maintenance</b>		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction Condition	"S"
b)	Condition of Surfacing	"S"
c)	Riding Quality	"S"
d)	Road Camber	"S"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES
f)	Constraction Joint provided or not(CC Pavement)	NO
g)	Compaction of flank/slope & raincuts if any	-
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	"S"
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-

  
 04/12/XX  
 (Signature)

4.12.20

NAME: Deepak Chandra Sinha  
 DESIGNATION : Junior Engineer