FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District: Mynger
Division: Munger		Length (km): 0.250
		got me N/1-80 to Dollarth boy ke Than
Scheme/Programme:	MAINTENANC	E MIR 3054
Package No.:		Road Id No.: 20803700851
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

110111	a case of: New Connectivity/Op gradation/ Mannethance	on Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	s/u S	
b)	Condition of Surfacing	s/u s	
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2, ;	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges	SISPANY	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	'3'
Satisfactory but requires Improvement (SRI)	Walter Francisco
Unsatisfactory (U)	,

(Signature)

MD. Altat Anwal

Scanned with CamScanner