

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Munger
Division : Munger	Length (km): 0.285
Name of the Road: NH-80 Balachola Mandir to Manmohan Bazar Gharhoke Huel Part Muncheiya ke Gharhoke	
Scheme/Programme: MAINTENANCE	MIR-3054
Package No.: 1	Road Id No.: 20803700853
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U R2
c)	Riding Quality	S/U R2
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No R2
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R2 Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	U

MD. Altaf Anwar

NAME:

(Signature)