## FIELD INSPECTION REPORT

Date of Inspection:05.12.2020 District:- Sitamar			District:- Sitamarhi		
Division:-RWD, Works Div. Pupri. Length (km):-2.165					
Name of	f the Road:- Na	aya Tola Serha vi	ia (PWD Road) up to Ra	hua Village	
Scheme	/Programme:-	MAINTEN	NANCE		
Package	e No.:- MR (30	)54)	Road Id No.: 316078		
Status o	of the Project:	Ongoing/Comp	leted/Under Maintenanc	e	
Work is	a case of:	New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be	e checked	Remarks	
1.	Pavement				
a)	Road Junction condition			✓S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			→S/U	
d)	Road Camber			-S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				
f)	Contraction .	✓Yes/No			
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U N	1
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	4
c)	Condition of railing/slab/approach for bridges			S/SRI/U	11
3.	Road Furniture				
a)	Whether sing Km & 200n provided and	¥es/No			
4.	Compliance l				
a)	Status of AT	No-			

## Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: - Prava Kr. Padel

(Signature)

DESIGNATION:- JE