

FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	DARBHANGA
Division:	DARBHANGA - 2	Length(Km):	7.0 Km
Name of Road:	JALF (SATHI CHAUK) TO BASANT		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No	
3	Compliance History		
a)	Status of ATR's & any others		
Overall Rating: - S			
✓ Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		✓	
Unsatisfactory (U)			

Name: Hare Ram
Designation: J.E. 06.12.2020

(Signature)

The work of B.T. portion completed
But flanks no complete Best work will be done soon