

FIELD INSPECTION REPORT

Date Of Inspection 3/12/2020		District Bhojpur
Division Piro		Length (km): 4.6 km
Name of the Road: Kori to Pandeypur Road.		
Scheme/Programme MAINTENANCE		
Package No.: RM/BH/PIR/19/0009		Road Id No.: 10401601038
Status of the Project : Ongoing/Completed/Under Maintenance		
Work is a case of : New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked	Remarks
1	Pavement	Ongoing Road
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name: Kamlesh Kumar

K. Kumar
3/12/2020
(Signature)

Designation J-E