

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Bhojpur
Division : Ara	Length (km): 5.906 Km
Name of the Road: Durgpur Shivpur Farhada Road to Sabalpur	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	(Work in Progress)
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Atunab
03/12/2020
(Signature) JE

NAME: