

FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	BUXAR
Division :		Length (km):	7.525 KM
Name of the Road:	KORANSARAI NAHAR PUL TO AKONI PUL PATH.		
Scheme/Programme:	MAINTENANCE	MAINTENANCE POLICY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No YES
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N-A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N-A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No YES
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Phu.
03/12/2020
J-G

Phu.
03/12/2020
A.E.

(Signature)

NAME: