

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Buxar
Division : RWD, Dumraon	Length (km): 1.250 Km
Name of the Road: Buxar Kailwar bandh to Jawahar Diyar	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U _{N/A}
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U _{N/A}
c)	Condition of railings/slab/approach for Bridges	S/SRI/U _{N/A}
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Akshay
02/12/2020
JE

(Signature)

NAME:

DESIGNATION: