FIELD INSPECTION REPORT

and the second s		23-12-20 Dis	trict:	Banus		
Date of L	ispection.	Lon	igth (km		7	
Division :	Banka.	LUI	igin (gm	7. 2. 75		in hath
Name of	the Road: Er	glish more shambhuf.	my wall	o Amerby	s ignosor	Z Patri
	Programme:	MAINTENANCE				
Package				: 2070	37008	28
The second secon	the Project:	Ongoing/Completed/Und				
	a case of:	New Connectivity/Up gra	adation/	Maintenance		
Sl. No.	102 (5) 64 TO 31 W 505	Parameters to be c	hecked	31 (15)		Remarks
1	Pavement					No. Dayle
a)	Road Junction condition			LS/U		
b)	Condition of Surfacing			√8/U		
c)	Riding Quality			VS/U		
<u>(i)</u>	Road Camber			.53	L87U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
1)		Joints provided or not (CC	Pavemen	t)		Yes/No
g)	Compaction	of flank/slope & raincuts if	any			Yes/No

b)	Condition of Abutment & Wing walls, Slab in RCC culver	ts S/SRI/U
c)	Condition of railings/slab/approach for Bridges	LS/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km stones/Pavement road markings are provided and maintain	& 200m Yes/No

Condition of head walls in Hume pipe culverts including its painting

S/SRI/U

Compliance History 4.

Cross Drainage

Status of ATR's & any others 21)

Overall Rating

g)

a)

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: J.E.