FIELD INSPECTION REPORT

	<u>r</u>	IELD MARI ECTI	days - bearing the same of the			
Date Of	f Inspection	2.12.202	>	District	BYOLDIN	-
Division	n PIRO,	Block-PiRO		Length (km):	1.75	
Name of the Road: I m provement of Hasan Bazar To					efardel Kute	2U'9
Scheme	e/Programme	MAINTENANCE				
Package	e No.: RMIBHIPIR	119/0002	Road Id N	io.: 104016	04122	
Status c	of the Project:	Ongoing/Completeted/Under Maintenance				
Work is	s a case of:	New Connectivity/U	Jp gradatio	n/Maintenance		
SI No.	Parameters to be checked				Remarks	
1	Pavment					
a)	Road Junction condition				✓S/U	
b)	Condition of Surfacing				VS/U	
c)	Riding Quality				√S/U	
d)	Road Camber				✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				Yes/No H	, P
f)	Contraction Joints provided or not (CC Pavement)				Yes/No N	A'I
g)	Compaction of flank/slope & raincuts if any				Yes/No	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U N	1· B
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				s/sri/u Ŋ	٠ ٩
c)	Condition of railings/slab/approach for Bridges				S/SRI/U ∱	1.8
3	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				V _{Yes/No}	
4	Compliance History					
a)	Status of ATR's & any others					
	J					
Overall Rating :		Satisfactory (S)		S		
		Satisfactory but requ	ires Improv	ement (SRI)		
		Unsatisfactory (U)			00	
Name:	-Manaj Shanlans	Problemsh.		©2/ (Sig	James (gnature)	
Desigin	nation ←J·£·					