

FIELD INSPECTION REPORT

Date of Inspection: _____

District: Amn

District: Amn

75 Km

Name of the Road: Yelwar Indira Road (Daulatpur Bony)

Length (km):

Scheme Programme: MAINTENANCE

2.91 km

Package No.:

Road Id No.:

1040608162

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of:

New Connectivity/Up gradation/Maintenance

Sl. No.

Parameters to be checked

Remarks

1. Pavement

a) Road Junction condition

✓ U

b) Condition of Surfacing

✓ U

c) Riding Quality

✓ S/U

d) Road Camber

✓ S/U

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.

Yes/No

f) Contraction Joints provided or not (CC Pavement)

✓ Yes/No

g) Compaction of flank/slope & raincuts if any

✓ Yes/No

2. Cross Drainage

a) Condition of head walls in Hume pipe culverts including its painting

S/SRI/U NON

b) Condition of Abutment & Wing walls, Slab in RCC culverts

S/SRI/U NON

c) Condition of railings/slab/approach for Bridge*

S/SRI/U NON

3. Road Furniture

a) Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained

200m ✓ Yes/No

4. Compliance History

a) Status of ATR's & any others

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

SRI

Unsatisfactory (U)

Priyanshu
Kumar

(Signature)

NAMU