

### FIELD INSPECTION REPORT

Date of Inspection : 10-08-2017 | District : Dhanbad | Length (km) : 1.0 Km  
 Division : Jharkhand | Scheme/Programme : Road Network Development

Name of the Road : PWD P.R. set A & Gopalpur | Scheme/Programme : MAIN MAINTENANCE | Package No. : 1608167

status of the Project : Ongoing + Completed Under Maintenance | Work in case of : New Connectivity Up gradation/ Maintenance

1. No. Parameters to be checked Remarks

1. Pavement ✓OK

(a) Road Junction condition ✓OK

(b) Condition of Surfacing ✓OK

(c) Riding Quality ✓OK

(d) Road Camber ✓OK

(e) Whether free from defects such as visible cracks, exposed aggregates in case of CT Pavement Yes/No ✓ N.D.A.

(f) Contraction Joints provided or not (CC Pavement) Yes/No ✓ N.D.A.

(g) Construction of Bank/slope & raincuts if any Yes/No ✓ N.D.A.

2. Cross Drainage

(a) Condition of head walls in stone pipe culverts including its painting S/SRI/U ✓ N.D.A.

(b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U ✓ N.D.A.

(c) Condition of railings/slabs/approach for Bridges S/SRI/U ✓ N.D.A.

3. Road Furniture

(a) Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained Yes/No ✓

4. Compliance History

(a) Status of ATR's & any others

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	U

Priyadarshini

(Signature)

NAM: