

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Chitapur</u>	
Division : <u>MA</u>		Length (km):	<u>5.6 km</u>
Name of the Road: <u>MH 20 GAWALDE to Tawalpur Pat</u>			
Scheme/Programme:		MAINTENANCE via Panchayat	
Package No.:		Road Id No.:	<u>10401608153</u>
Status of the Project:		Ongoing/Completed/Under Maintenance ☒	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		Mo

Overall Rating :

Satisfactory (S)		-
Satisfactory but requires Improvement (SRI)		SRI
Unsatisfactory (U)		-

Prakash Kumar
(Signature)

AMEI