

FIELD INSPECTION REPORT

Date of Inspection :		District:	
Division : <i>...</i>		Length (km):	<i>9.8 km</i>
Name of the Road: <i>MH 30 Kalyan Nagar Young Bahadur</i>			
Scheme/Programme: <i>MAINTENANCE</i>			
Package No.:		Road Id No.:	<i>10401ACB153</i>
Status of the Project:		Ongoing/Completed Under Maintenance ☒	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	
c)	Riding Quality	☒ S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	☒ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No	
g)	Compaction of flank/slope & re-incuts if any	☒ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	☒ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	<i>ND</i>	

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	<i>S</i>
Unsatisfactory (U)	<i>S</i>

13/12/2019
M/W
 (Signature)

NAME: