

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: Bhujpur, Ar.
 Division: Jagdishpur, Ar. Length (km):
 Name of the Road: P.W.D. Road Se Jamur, Baruna Dalpatpur Late Ruchanpur
 Scheme/Programme: MAINTENANCE Old Under maintenance
 Package No.: Road Id No.: 10401708063
 Status of the Project: Ongoing/Completed/Under Maintenance Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
1.1	Road Junction condition	S/U
1.2	Condition of Surfacing	S/U
1.3	Riding Quality	S/U
1.4	Road Camber	S/U
1.5	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
1.6	Contraction Joints provided or not (CC Pavement)	Yes/No
1.7	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
2.1	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
2.2	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
2.3	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
3.1	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
4.1	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Gyanendra Mishra

06/12/2020
 (Signature) J.E.