

FIELD INSPECTION REPORT

Date of Inspection: 04-12-2020. District: Bhajpur, Arunachal Pradesh
 Division: B.W.D.W.D - Jagdishpur, Arunachal Pradesh Length (km): 4.00 Km.
 Name of the Road: NH-84 Ranisagar SE B.W.D. More Bhadrali
 Name/Programme: MAINTENANCE Old - Under maintenance

Package No.: Road Id No.: 10401708065
 Status of the Project: Ongoing/Completed/Under Maintenance Under maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
2.	Road Junction condition	✓
3a.	Condition of Surfacing	S/U
3b.	Riding Quality	S/U
4.	Road Camber	S/U
5.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
6.	Contraction Joints provided or not (CC Pavement)	Yes/No
7.	Compaction of flank/slope & raincuts if any	Yes/No
8.	Cross Drainage	
9a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
9b.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
9c.	Condition of railings/slab/approach for Bridges	S/SRI/U
10.	Road Furniture	
11.	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
12.	Compliance History	
13.	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Gayanand Nirala

04/12/2020
 (Signature) JE