

FIELD INSPECTION REPORT

Date Of Inspection		3/12/2020	District	Bhojpur
Division		Piro	Length (km):	1.0 km
Name of the Road:		TOI TO Trikaud.		
Scheme/Programme		MAINTENANCE		
Package No.:		RM/BH/PIR/19/0010	Road Id No.: 10401802035	
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked			Remarks
1	Payment			Work Not Started
a)	Road Junction condition			S/U
b)	Condition of Surface			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No
f)	Contraction Joint provided or not (CC Pavement)			Yes/No
g)	Compaction of Bank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of fillings/slab approach for Bridges			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stone Pavement markings are provided and maintained			Yes/No
4	Compliance history			
a)	Status of AT & any others			

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name:

Kamlesh Kumar

K. Kumar
3/12/2020
(Signature)

Designation

J-E.