

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Buxar
Division : Dumaraon	Length (km): 0.500 km.
Name of the Road: Chandrapur Bazar to Chandrapur	
Scheme/Programme: MAINTENANCE New maintenance policy	
Package No.: MR-N/19-20, Dumaraon/3	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME:

DESIGNATION:

3/12/20
J.E.
Brahm Jais

(Signature)