

**FIELD INSPECTION REPORT**

Date of Inspection : 03-12-2020

Division : Dumaraon District: Buxar

Name of the Road: NH 84 Deokuli school to Kothia Length (km): 1.600 km.

Scheme/Programme: MAINTENANCE New maintenance Policy

Package No.: MR-N/19-20 Dumaraon/3 Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance Completed

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N-A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N-A.
g)	Compaction of flank/slope & raincuts if any	Yes/No N-A.
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N-A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N-A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A.
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*Inspected by*  
*21/12/20*  
*J. E.*  
*Braham/Bux*

(Signature)

NAME:

DESIGNATION: