

FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	BUTAR
Division :	DUMRAON	Length (km):	10.730 KM
Name of the Road:	TEDHAKI PUL TO MUNGASI.		
Scheme/Programme:	MAINTENANCE	NEW MAINTENANCE POLICY	
Package No.:	HR-N/19-20 DUMRAON/01	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Completed
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓ NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U H.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U H.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U H.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No YES
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Attn:
03/12/2020
J.E.

For
3/12/2020
A.E.

for
3/12/2020
EE
(Signature)

NAME: