

## FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	Works (DII) Darbhanga -2	Length(Km):	4.40 KM.
Name of Road:	Katka PWD to paira Jahaal via Mohanpuz.		
Scheme/Programme:	Maintenance MR-3054.		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance —		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank /slope & raincuts if any	✓Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
<b>3</b>	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	
Overall Rating:		

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name: KUMAR CHANDRAS  
Designation: ASST ENGINEER.

(Signature)  
सहायक अभियन्ता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, सिंहबाड़ा