FIELD INSPECTION REPORT

	FIELD INSPEC	The state of the s	
spection:	1/12/2020	District: GAYA	
A CONTRACTOR OF THE PARTY OF TH		Length (km): 9.60	
the Road: G-	TREAD GRAM B	ARA TO MANFAR AWASIA	VID JACONIO
rogramme:	MAINTENANCE	3637	<u></u>
No.:	,		A COLUMN TO THE PARTY OF THE PA
1 de la Maintendice			
			Remarks
Parameters to be checked		and the second second	
Pavement			
Road Junction condition			\\$/U
			√S/U
			√5/U
1			~\$/U
Road Camber			ennumental de la companya de la comp
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No-
			Yes/No
Compaction of flank/slope & raincuts if any			Yes/No
Cross Drainage			
Condition of head walls in Hume pipe culverts including its painting			√S/SRI/U
The first of the f			~S/SRI/U
Condition of railings/slab/approach for Bridges			S/SRI/U
Road Furni	ture		
Whether significant stones/Paver	gn boards/informate ment road markings	ory/cautionary Board/km & 200m are provided and maintained	Yes/No
Compliance	History		HO:
	Commission of the state of the		Ho
	SHER the Road: Grogramme: No.: the Project: a case of: Pavement Road Junction Condition of S Riding Quality Road Camber Whether freaggregates in Contraction J Compaction of Condition of	SHERCHATE the Road: GTRAM B Programme: MAINTENANCE No.: the Project: Ongoing/Completed a case of: New Connectivity/U Parameters to Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects surfacing aggregates in case of CC Pavemer Contraction Joints provided or not Compaction of flank/slope & rain Cross Drainage Condition of head walls in Hume Condition of Abutment & Wing of Condition of railings/slab/approa Road Furniture Whether sign boards/informate	SHERCHATE. Che Road: GTREAD GRAM BARATE MAN FAR AWASIA Programme: MAINTENANCE 30 559 No.: The Project: Ongoing/Completed/Under Maintenance The Condition of Surfacing Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating .

	10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	will will will be the control of the
2.K.W.4.E.S.	Satisfactory (S)	V(S)
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
100	The state of the s	The second secon

(Signature)

NAME: MD. YAS) N. AMSARI DESIGNATION: T. E.