

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020		District: JEHANABAD
Division: Jehanabad		Length (km): 3.50 km
Name of the Road: Repair of Road from Nadul Bazar to Madhura Sima		MAINTENANCE
Scheme/Programme:		Road Id No.:
Package No:		
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
S.N	Parameters to be checked	Remarks
1.	Payment	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Doesn't pertain to Jehanabad division, it belongs

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

to Madhura
Division

03/12/2020
Signature

NAME:

CHANDAN KUMAR

DESIGNATION:

T. G.