

FIELD INSPECTION REPORT

Date of Inspection :	3.12.20	District:	Jehanabad
Division :	Jehanabad	Length (km):	S-220
Name of the Road:	SIKARIYA TO KAMDHO BIGHA		
Scheme/Programme:	MAINTENANCE		
Package No.:	—	Road Id No.:	✓
Status of the Project:	Ongoing Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU ✓
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	SU ✓
d)	Road Camber	SU ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes No ✓
g)	Compaction of flank/slope & raincuts if any	Yes No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

(Signature)

NAME: BINDU KUMAR
DESIGNATION: AE