

(Block - Shahkunda)

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 2.68 Km.	
Name of the Road : Shahkunda Block under Tola More to Sighpur			
Scheme / Programme :		MAINTENANCE	
Package No. / Group No - 09		Road Id No. : 20703201062	
Status of the Project :		Ongoing / Completed / Under Maintenance	
Work is a case of :		New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating :			
	Satisfactory (S)	—	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	—	

Note : work in progress is very slow.

NAME : Radha Raman Singh
DESIGNATION : Assistant Engineer

Signature
05/12/20