

FIELD INSPECTION REPORT

Date of Inspection: 6.12.20.		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 2.40 Km.	
Name of the Road: Abjuganj Kumathia Road.			
Scheme / Programme: MAINTENANCE			
Package No.:		Road Id No.: 20763208213.	
Status of the Project: Ongoing / Completed / Under Maintenance			
Work is a case of: New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NA
4.	Compliance History		
a)	Status of ATR's & any others	NA	
Overall Rating:			
	Satisfactory (S)	NA	
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		

Not - This Road has been taken under class-2 3054 MK and work is under five year maintenance work is going under five year maintain At present.


NAME:

DESIGNATION:

Rajkishor Rastogi
A.E

(Signature)


6.12.2020
A.E


6.12.20
m