

FIELD INSPECTION REPORT

Date of Inspection: 6.12.2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 2.50 km.	
Name of the Road: Sultenganj to Sak Kund. Road.			
Scheme / Programme: MAINTENANCE			
Package No: —		Road Id No.: 20703208215	
Status of the Project: Ongoing / Completed / Under Maintenance			
Work is a case of: New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	N/A
g)	Compaction of flank/slope & rainouts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI / U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S SRI / U	N/A
c)	Condition of railings/slab/approach for Bridges	S SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating:			
	Satisfactory (S)	—	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	—	

NAME:

Ratikishor Pratih

DESIGNATION:

A.E

(Signature)

6.12.2020
A.E

AS
Ghosh
M