FIELD INSPECTION REPORT

T	uspection: 0	E 19. 2020	District: Banka	
Date of Inspection: $05.12.2020$ Division: $89nkg-1$			Length (km): 5.3	
Name of	the Road: As	ungani RCD Road	to modard rukhant	jus.
Scheme/l	Programme:	MAINTENANCE		
Package	No.: RM/B	A /BAH/19/0005	Road Id No.: 207035010	17
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
alamata ka ka mata mata mata mata mata mat	Payament			The second second

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	\S/U	
b)	Condition of Surfacing	\ 8/U	
c)	Riding Quality	√8/U	
d)	Road Camber	8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	1 + - 1 + -	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	Satistactory
Satisfactory but requires Improvement (SRI)	1 districts of
Unsatisfactory (U)	

(Signature)

NAME: PRITAM KUMAR

DESIGNATION: AE