

FIELD INSPECTION REPORT

Date of Inspection: 09.11.2020	District: Palna
Division: B&H	Length (km): 2.0 km
Name of the Road: PWD Road to Kanchak Agrera (CPWD Road to Kanchak Agrera)	
Scheme/Programmer: MAINTENANCE	Road Id No.:
Package No.:	Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank slope & ditches if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Drain pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI
c)	Condition of railings/slab approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Provision road markings are provided and maintained	✓ No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SII)	
Unsatisfactory (U)	

Bishu Pratap Singh
JUNIOR Engineer.
NAME:

Bishu Pratap Singh
(Signature) D.E