

FIELD INSPECTION REPORT

Date of Inspection : 07-12-2020	District: Banka
Division : RWD Banka-02	Length (km): 2.160 Km
Name of the Road: Boush Irrigation Dam Road to Jhaz	
Scheme/Programme:	MAINTENANCE (New Maint. Policy 2018)
Package No.: RM/BA/BAM/20/0001	Road Id No.: 2070350 2042
Status of the Project:	✓ Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S) ✓	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
07/12/2020

NAME: Krishna Kumar Sinha
DESIGNATION: Executive Engineer
RWD, Banka-2