

FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020	District: Madhubani
Division : Benipatti	Length (km): 11.900 km
Name of the Road: Loha To Dhaktari	
Scheme/Programme: MAINTENANCE	
Package No.: RM/MA/BEN/19/02	Road Id No.: NEA 22000129
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

↑ WORK NOT STARTED TILL DATE ↓

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

} N/A

NOTE:- (i) Site clearing work in progress.
(ii) Pot Patch work is pending.
(iii) SDBC work is pending.

Vinay
5-12-2020
(Signature)

NAME: VIKASH CHANDRA VIDYARTHI

DESIGNATION: JE.