

FIELD INSPECTION REPORT

Date of Inspection : 05-12-20

District: Madhubani

Division : Madhubani

Length (km): 19.750 km.

Name of the Road: Chamba to Laxmipur

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project:

☒ Ongoing ☐ Completed ☐ Under Maintenance

Work is a case of:

☒ New Connectivity ☒ Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/A ✓
b)	Condition of Surfacing	S/A ✓
c)	Riding Quality	S/A ✓
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No ATR


Rectification work yet to be started

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Ram Nath Singh.
J.E.

NAME:


5.12.20
(Signature) J.E.